Black sheet, PMTs, Testing:

1 Visualization checks so far:

2 Black sheet light tightness, all detector configurations

3 All black sheet situated where we expect it to be
(ie. not getting in the way of PMTs)

4 All PMTs are recording hits correctly